



COVER-ALL

Product Datasheet

sales@coverallsupplier.co.za
082 608 4437 (JHB)
coverallsupplier@telkomsa.net
072 689 2209 (DBN)

UNIT, 2 MLT HOUSE, 6 BRUNING
ROAD, Jacobs, Bluff

FIXCHEM



FIXCHEM



Page 5

SURFACE PREPARATION FOR FIXCHEM APPLICATION

Ensure all surfaces are clean dry, sound, and free from all laitance, fungal growth, grease, oil, or loose and flaking particles.

BONDING/PRIMING

Prime porous surfaces with a neat coat of Cover-All Bonding Liquid

MIXING

Stir well before use.

COVERAGE

Coverage: 2.1 ℓ/m^2 full system.

APPLICATION

1st coat- apply by brush/roller using 1 ℓ/m^2 together with Cover-All membrane into the wet coat, avoiding bubbles or wrinkles. The membrane overlaps a minimum of 100 mm on end laps and 75 mm on side laps.

2nd coat: once 1st coat has dried (2 – 3 hours), apply 2nd coat by brush/roller using 0,5 ℓ/m^2 and ensure the membrane is fully saturated.

3rd coat: once 2nd coat has dried, apply 3rd coat at different angle to 2nd coat using 0,5 ℓ/m^2

Drying time @ 25 °C

Touch dry: 1 hour

Hard dry: 24 hours

Full cure: 7 days

CLEANING

Whilst still wet, clean equipment with water by washing it with soap & water.

CAUTION

Membrane must be used. Always ensure that Fixchem is applied to well-drained roofs.

PROTECTION ON COMPLETION

Whilst Fixchem is designed for an extended life, it is important to apply a maintenance coat of Fixchem every 3 to 4 years.

PACKAGING

Available in 5-litre



Coverall Industrial
Supplier